
From: Larry [REDACTED]
Sent: Friday, May 12, 2017 7:42 AM
To: Je vacation; Rich Kahn
Subject: Fwd: G550 sn 5173

Jeffrey,
<iv id="AppleMailSignature">See attached original number from Eric., Appears Eric increased his price for recover of the 6 main Cabin seat=,.
Originally he quoted \$116,800 for all 8 seats (=14,600 each seat)

----- Forwarded message -----

From: Eric Roth=[REDACTED]
Date: Tue, Apr 25, 2017 at 12:13 PM
Subject: RE: G550=sn 5173
To: "jeffrey E." <je=vacation@gmail.com <mailto:jeevacation@gmail.com> >

Date: 4.24.17

Client: JE

Aircraft: G550

Serial Number: 5173

soft goods

Price

\$ 3,767.=0

\$ 3,294.=0

203 Upper Side Wall Panels

\$ 3,256.=0

204 Lower Side Wall Panels

\$ 5,713.=0

205 Glareshield

\$ 2,133.=0

206 Bulkhead Panels

= \$ 3,058.=0

207 Center pedestal

= \$ 1,074.=0

208 Crew Seats

\$ 11,230.00

209 Control column boots

\$ 1,459.=0

210 Jepp storage

\$ 824.00

211 Crew privacy curtain

\$ 2,022.=0

225 Floor Covering (Cockpit) <=p> \$ 4,419.=0

230 Cockpit Paint / Touch up <=p> \$ 1,473.=0

Price

301 Headliner Panels

\$ 2,620.=0

304 Airstair Treatment <=p> \$ 4,580.=0

311 Fwd Lavatory Upper Sidewall Panel

\$ 1,098.=0

314 R/H Fwd Lav Potty Seat

\$ 2,533.=0

320 Jumpseat

\$ 8,425.=0

325 Floor Covering (Entryway) =/p> \$ 1,272.=0

Price

401 Headliner Panels

\$ 9,825.=0

402 R/H & L/H PSU / Valance Panels</=>

\$ 13,535.00

406 Window Line Panels

\$ 13,915.00

409 Lower Side Panels

\$ 14,730.00

412 Fwd Cabin Bulkheads

\$ 3,973.=0

416 Aft Cabin Bulkheads

\$ 3,973.=0

420 Cabin Single Seats (8)

\$ 116,800.00

422 Divan(s) -2-

\$ 49,190.00

423 Divan End Arm Cabinets

\$ 4,392.=0

425 Floor Covering

\$ 38,235.00

Price

501 Headliner Panels

\$ 1,897.=0

525 Floor Covering (Galley)</=> \$ &=bsp; 636.00

Price

601 Headliner Panels

\$ 1,897.=0

606 Potty Seat & Shroud

\$ 3,794.=0

611 Aft Lavatory R/H Closet</=> \$ 4,580.=0

612 Aft Lavatory L/H Closet</=> \$ 4,580.=0

625 Floor Covering (Aft Lavatory)

\$ &=bsp; 848.00

Price

701 Recover Panels

\$ 11,605.00

703 Baggage Door Vinyl Flap

\$ &=bsp; 737.00

725 Floor Covering

\$ 3,772.=0

730 Paint / Touch Up

\$ 3,505.=0

Price

801 Remove Interior / Inc. Inspection=>

\$ 14,500.00

802 Install Interior / Detail in Aircraft=>

\$ 33,050.00

803 Fire Blocking (jump, 3 materials in main)</=>

\$ 50,820.00

804 Vertical / Composite Burn Cert.

\$ 7,566.=0

807 Maintenance Runner(s)

\$ 2,134.=0

829 Engineering / Certificate=/p> \$ 1,700.=0

836 Exterior Paint - ballast for paint</=>

\$ 5,020.=0

woodwork & finish

Price

801 Remove Interior / Inc. Inspection=u>

\$ 11,850.00

802 Install Interior / Detail in Aircraft=/u>

\$ 43,653.00

806 Woodwork (all plus finish)=/span>

\$ 373,267.00

808 Install Placards

Hangar Rent

modifications

Price

317 Forward Crew Galley

\$ 5,267.=0

402 R/H & L/H PSU / Valance Panels - closeout<=>

\$ 8,425.=0

406 Window Line Panels

\$ 7,789.=0

407 R/H & L/H Drinkrail / Ledges=/span>

\$ 3,572.=0

410 Side Wall Tables (rare earth mag, supports)=/u>

\$ 19,865.00

417 Aft Cabin Curtain (acoustic, track, magnets)

\$ 9,050.=0

424 Credenza

\$ 14,975.00

427 Aft L/H Closet (new cabin)

\$ 22,340.00

502 Aft R/H Galley

\$ 15,410.00

503 Aft L/H Galley

\$ 21,090.00

602 L/H PSU / Valance Panel (mirror, hinged)

\$ 6,115.=0

605 Aft Lavatory Vanity

\$ 13,860.00

606 Potty Seat & Shroud (split, cavity)<=>

\$ 5,490.=0

611 Aft Lavatory R/H Closet (toilet paper)<=>

\$ 2,071.=0

814 110 VAC Outlets (fwd crew galley)

\$ 3,761.=0

815 Lighting System

\$ 6,740.=0

829 Engineering / Certification / structural =& elect.

\$ 85,490.00

options

Bid Price

\$ 56,470.00

Bid Price

405 Inner Window Shades

\$ 38,640.00

Bid Price

\$ 10,840.00

Bid Price

\$ 27,610.00

Best Regards,

Eric

ERIC H. ROTH

2221 Smithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779

From: jeffrey E. [mailto:jeevacation@gmail.com]

Sent: Tuesday, April 25, 2017 10:34 AM

To: Eric Roth <[REDACTED]>

Subject: Re: G550 sn 5173

????

On Tue, Apr 25, 2017 at 10:07 AM Eric Roth <[REDACTED]>

Jeff,

Do you know what the estimated cost is to upgrade his Airshow 4000 to Revision 2?

What about the cost to direct wire an HD=I cable from Airshow to the TV so he has hi-def airshow?</=>

If you need any specific info on the air=raft, let me know asap.

Thank you!

Best Regards,

Eric

ERIC H. ROTH=span style="font-size:10.0pt;font-family:"Arial",sans-serif;color:#644e39"> | PRESIDENT

=u>

<ma [REDACTED]

2221 Sm=thtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779

--

please not=

The information contained in this communication is

constitute inside information, and is intended only for the use of the addressee. It is the property of JEE Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to

jeevacation@gmail.com <mailto:jeevacation@gmail.com> , and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

--

=nbsp; please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE. Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com <mailto:jeevacation@gmail.com> , and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved

=