

---

**From:** Ann Rodriguez <[REDACTED]>  
**Sent:** Wednesday, April 26, 2017 4:34 PM  
**To:** Jeffrey  
**Subject:** FYI: Danny & Chris

Hey Bossman,

Danny installed the new oil sensor on the generator over at GSJ. He said the battery needs to be jumped with jumper cable because the battery is charging low

I told Danny and Chris (they were together and I was on speaker) that Tap said not to jump the generator because it's an electrical generator and it could burn out other things. I told them that tap is sending over a new battery for the generator but Danny V. is still insisting that he could jump it

```
Ann R.<?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN"
"http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
  <key>conversation-id</key>
  <integer>46127</integer>
  <key>date-last-viewed</key>
  <integer>0</integer>
  <key>date-received</key>
  <integer>1493224536</integer>
  <key>flags</key>
  <integer>8590195713</integer>
  <key>gmail-label-ids</key>
  <array>
    <integer>6</integer>
    <integer>2</integer>
  </array>
  <key>remote-id</key>
  <string>708608</string>
</dict>
</plist>
```